HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum To Decatur House 748 Jackson Place, NW Washington District of Columbia HABS No. DC-16

Photographs DC-16-1 through DC-16-15 have been transmitted to the Library of Congress.

Photographer Unknown, Date Unknown

DC-16-16 ²⁴	EAST	FRONT,	VIEW	FROM	NORTHEAST
------------------------	------	--------	------	------	-----------

DC-16-21 ²⁹	EAST	FRONT,	DETAIL	OF	ENTRANCE	AND	FIRST	FLOOR,	FROM	THE
<u> </u>		HEAST							10-1	

DC-16-22 ⁵⁰	БТРОП	EI COD	3.73° 135.7	D3 CO	m^	ENTON MOE	DOODLAN
DC-10-22	LIKSI	FLOOR,	ATEM	EAST	TO	ENTRANCE	DOORWAY

DC-16-3Q 38 SECOND FLOOR, DRAWING ROOM, DETAIL OF PARQUET FLOORING, VIEW WEST

DECATUR HOUSE HABS No. DC-16 INDEX TO PHOTOGRAPHS (2)

DC-16-3139 DC-16-32 40 ATTIC, HALL, VIEW SOUTHWEST TO DOORWAY (BEFORE REMODELING) DC-16-334 ATTIC, HALL, VIEW NORTHEAST TO DOORWAY (BEFORE REMODELING) DC-16-3442 ATTIC, HALL, VIEW SOUTHEAST TO DOORWAY (BEFORE REMODELING) DC-16-36 43 ATTIC, GENERAL VIEW TO SOUTHWEST (DURING REMODELING) DC-16-36 44 ATTIC, GENERAL VIEW TO SOUTHWEST CORNER (DURING REMODELING) DC-16-37 45 ATTIC, VIEW EAST TO SOUTHEAST CORNER

SECOND FLOOR, SOUTHWEST ROOM, VIEW SOUTHEAST

DC-16-3846 ATTIC, VIEW SOUTH TO SOUTHEAST END

DC-16-39 47 ATTIC, TYPICAL OUTRIGGING FOR EAST AND WEST WALLS

DC-16-49 48 ATTIC, TYPICAL OUTRIGGING , VIEW TURNING CORNER

DC-16-4149 ATTIC, TYPICAL OUTRIGGING FOR NORTH AND SOUTH WALLS

DC-16-4250 ATTIC, UPPER CRAWL SPACE

DC-16-435/ ATTIC, UPPER CRAWL SPACE, DETAIL OF QUEEN POST

HABS DC, WASH, 28-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO
DECATUR HOUSE (NATIONAL TRUST FOR HISTORIC PRESERVATION)
748 Jackson Place, NW
Washington
District of Columbia

HABS No. DC-16

DC-16-1 through DC-16-43 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, 1976

52

DC-16-44 (CT)

EAST FRONT, VIEW FROM SOUTHEAST